

System ID: 133

Date of Inspection: 11/14/2011

# **County of Yuma** Contract: 00074786

001 **COUNTY OF YUMA** Member:

028 SAN LUIS LIBRARY BRANCH Site: Building:

001 LIBRARY 1075 NORTH 6TH AVENUE **SAN LUIS, AZ 85349** 





### **Valuation Summary**

\$5.397.000 **Building Cost of Reproduction New** (\$184 per SF) **Contents Cost of Reproduction New** \$2,483,000 (\$85 per SF) Land Improvements Cost of Reproduction New

## **Construction Components**

ISO Class: 2 - JOISTED MASONRY (35 %), 4 - MASONRY NON-COMBUSTIBLE (65 %),

CURTAIN WALL, GLASS (24 %), STUCCO ON MASONRY (40 %), STUCCO ON FRAME (36 %) **Exterior Wall Type:** 

Heating: ROOFTOP UNIT (HEATING) ( 100 % ) Cooling: ROOFTOP UNIT (COOLING) (100%) Roof Material: SINGLE-PLY MEMBRANE (100 %)

Roof Pitch: FLAT (50 %), LOW (2:12 TO 6:12 PITCH) (50 %) Elevators: Passenger: 1 Freight: 0

## **Description**

Year Built: 2010 **Number of Stories:** 2

Average Story Height: 15

Square Footage: Super Structure: 29,291 Sub Structure:

29,291 Total:

#### **Protection**

Manual Fire Alarm: Υ Υ Automatic Fire Alarm: Sprinklers: Entry Alarm: Fire Dept Paid / Volunt: **Protection Class:** 

## **Exposure**

Latitude: N 32-29-50.2 Longitude: W 114-46-06.0

Flood Zone:

Flood Zone Certificate: BFE: 0 Distance to Coast: 0

#### **Miscellaneous Additional Features**

BALCONIES; SURVEILLANCE CAMERA; PANIC BUTTONS

Printed: 2/7/2012 11:50:49 AM Page 1 of 1